

J. Gilbert Submission – Water Trigger Review

Mr John Jenkyn Chinchilla photographs

Methane bubbling through soil visible in puddles Jenkyn property 26/1/2016



Land subsidence Jenkyn property



Subsidence Chinchilla QGC pipeline corridor



Condamine River Chinchilla bubbling methane (combusting Nov-Dec 2015- NOT PHOTOSHOPPED) and radon gas



Toxic groundwater seeping from through soil, near Jenkyn property Chinchilla

